



\*Errata: 470 Ohms Resistor is missing in the PCB layout. Add a 470 Ohms Resistor in series with L4.  
Follow the Schematic.

